CAUTION: PROTECT BALLS AND RACES FROM SAWDUST, DIRT, PAINT, ETC. SHOULD BEARING BECOME "ROUGH" FROM DIRTY RACES, FLUSH THOROUGHLY WITH HOT SOAPY WATER, RINSE, OVEN DRY AND RE-OIL.



SECTION "A-A"



PART STAMPED WITH TRIANGLE NAME STAMP

DET	PART NUMBER	DESCRIPTION	AMT
3	BALLS6	BALL	1
2	1068	RACE-PLAIN	1
1	1067	RACE-LOCKING	1

TRIANGLE MANUFACTURING CO.
OSHKOSH, WI.

NAME	6" L.S.B.
USED IN	////
DATE	4-14-76
DRAWN	SP
CHECKED	MJK
SCALE	1 / 1
PART NO.	6C
FIT	////
PLATING	ELECTRO-GALV
MATERIAL	SEE DET

ALL DIMS ±.020 UNLESS SPECIFIED

CHANGE LEVEL	
E	01-05-94