

CAUTION: PROTECT BALLS AND RACES FROM SAWDUST, DIRT, PAINT, ETC. SHOULD BEARING BECOME "ROUGH" Ⓜ FROM DIRTY RACES, FLUSH THOROUGHLY WITH HOT SOAPY WATER, RINSE, OVEN DRY AND RE-OIL.



0.281 [7.14]- 4 HOLES IN PLAIN RACE
0.281 [7.14]- 4 HOLES IN LOCKING RACE

Ⓜ 0.203 [5.16] 4-HOLES IN PLAIN RACE

0.219 [5.56]

THERE WILL BE 2 TO 4 BALLS LEFT OUT DUE TO MANUFACTURING PROCESS.

Ⓜ



PART STAMPED WITH TRIANGLE NAME STAMP

DET	PART NUMBER	DESCRIPTION	AMT
Ⓜ	3	BALLS12	BALL 1
	2	1866	PLAIN RACE 1
	1	1865	LOCKING RACE 1
C TRIANGLE MANUFACTURING CO. DSHKOSH, VI.			

NAME 12" LAZY SUSAN BRG. ASS'Y		USED IN	
PLATING	ELECTRO GALV	DATE	7-14-76
MATERIAL	SEE DETAIL	DRAWN	LML
ALL DIMS. ±.003 UNLESS OTHERWISE SPECIFIED		CHECKED	SP
SCALE		1 / 1	PART NO.

12C

CHANGE LEVEL
P 107-31-06